

FLORIDA POWER CORP P BAYN .D
3201 34 ST SOUTH
SAINT PETERSBURG FL 33711



Mailgram



4-027304S349 12/15/79 ICS IPMMTZZ CSP WSHB
8138664540 MGM TDMT SAINT PETERSBURG FL 230 12-15 0422P EST

MR HAROLD R DENTON
7920 NORFOLK AVE
BETHESDA MD 20014

SUBJECT: CRYSTAL RIVER UNIT 3 DOCKET NUMBER 50-302 OPERATING LICENSE
NUMBER DPR72 LESSONS LEARNED SHORT-TERM REQUIREMENTS

DEAR MR DENTON

ON DECEMBER 14, 1979 MR ANDREW H HINES AND MR GEORGE C MOORE OF
FLORIDA POWER CORPORATION TELEPHONED YOU TO EXPRESS THEIR CONCERN
OVER NRC'S CURRENT ACTION PLAN REGARDING LESSONS LEARNED SHORT-TERM
REQUIREMENTS IMPLEMENTATION. YOUR PROPOSED COMPLIANCE DATE OF JANUARY
31, 1980 RAISES SERIOUS CONCERNS IN THE ENTIRE STATE OF FLORIDA IN
TERMS OF SYSTEM RELIABILITY. TO MEET THIS COMPLIANCE DATE CRYSTAL
RIVER UNIT 3 MUST BE REMOVED FROM SERVICE TO IMPLEMENT THE PORV AND
SAFETY VALVE POSITION INDICATION MODIFICATION.

AS STATED IN OUR NOVEMBER 17, 1979 RESPONSE TO YOU FLORIDA POWER
CORPORATION'S PROJECTED WINTER PEAK LOAD OCCURS IN THE JANUARY AND
FEBRUARY TIME FRAME. A GENERATION SHORTFALL WOULD RESULT IF CRYSTAL
RIVER UNIT 3 WERE OUT OF SERVICE DURING THE PROJECTED WINTER PEAK. IN
ADDITION DUE TO THE UNIQUE TRANSMISSION CAPABILITIES THE OVERALL
SYSTEM RELIABILITY PROBLEM IS NOT ALLEVIATED WITH PURCHASED POWER IF
IT WERE AVAILABLE. FLORIDA POWER CORPORATION IS CONDUCTING FURTHER
SYSTEM LOAD ANALYSES TO PROVIDE ADDITIONAL SUPPORTING DOCUMENTATION.
THIS INFORMATION WILL BE PROVIDED TO YOU AS SOON AS POSSIBLE. YOUR
ATTENTION TO THIS MATTER IS REQUESTED PRIOR TO THE ISSUANCE OF
PROPOSED ORDERS FOR CRYSTAL RIVER UNIT 3.

PATSY Y BAYNARD MANAGER
NUCLEAR SUPPORT SERVICES
FLORIDA POWER CORP

16:22 EST

MGMCOMP MGM

→ ADVANCE
CY
- Mike Collins

ADH
1/10