



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

Docket Nos. 50-289
50-320

SEP 14 1979

Metropolitan Edison Company
ATTN: Mr. J. G. Herbein
Vice President - Generation
P. O. Box 542
Reading, Pennsylvania 19603

Gentlemen:

Subject: Combined Inspection 50-289/79-07 and 50-320/79-06

This refers to the inspection conducted by Mr. W. Madden of this office on March 19-23, 1979 at Three Mile Island Nuclear Station, Units 1 and 2 of activities authorized by NRC License Nos. DPR-50 and DPR-73 and to the discussions of our findings held by Mr. Madden with Mr. J. Logan of your staff at the conclusion of the inspection, and to a subsequent telephone discussion between Mr. Madden and Mr. J. Stacy of your staff on March 27, 1979.

Areas examined during this inspection are described in the Office of Inspection and Enforcement Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, it appears that one of your activities was not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. This item of non-compliance has been categorized into the levels as described in our correspondence to you dated December 31, 1974. This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within twenty (20) days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you and the results achieved; (2) corrective steps which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of findings of your control and accounting procedures for safeguarding special nuclear materials and your facility security procedures are exempt from disclosure; therefore, the enclosures to this letter, and your response to this letter will not be placed in the Public Document Room and will receive limited distribution.


8002290

494

SEP 14 1979

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



Walter G. Martin, Chief
Safeguards Branch

Enclosures:

1. Appendix A, Notice of Violation (Contains 2.790 Info)
2. Office of Inspection and Enforcement Combined Inspection
Report Numbers 50-289/79-07; 50-320/79-06 (Contains 2.790 Info)

cc:

- E. G. Wallace, Licensing Manager (w report cover sheet only)
- J. J. Barton, Project Manager (w report cover sheet only)
- R. C. Arnold, Vice President - Generation (w report cover sheet only)
- L. L. Lawyer, Manager - Generation Operations (w report cover sheet only)
- G. P. Miller, Manager - Generating Station - Nuclear (w report cover sheet only)
- J. L. Seelinger, Unit 1 Superintendent (w report cover sheet only)
- J. B. Logan, Unit 2 Superintendent (w report cover sheet only)
- W. E. Potts, Unit 1 Superintendent - Technical Support (w report cover sheet only)
- G. A. Kunder, Unit 2 Superintendent - Technical Support (w report cover sheet only)
- I. R. Finfrock, Jr. (w report cover sheet only)
- Mr. R. Conrad (w report cover sheet only)
- G. F. Trowbridge, Esquire (w report cover sheet only)
- Miss Mary V. Southard, Chairman, Citizens for a Safe Environment (w report cover sheet only)