POK



## UNITED STATES NUCLEAR REGULATORY COMMISSION REGION V

1990 N. CALIFORNIA BOULEVARD SUITE 202, WALNUT CREEK PLAZA WALNUT CREEK, CALIFORNIA 94596

MAR 1 0 1980

Docket No. 70-1257

Exxon Nuclear Company 2101 Horn Rapids Road Richland, Washington 99352

Attention: Dr. R. Nilson, Manager

Quality Assurance and Licensing

Gentlemen:

This letter refers to the inspection of your activities authorized under NRC License No. SNM 1227 conducted by Messrs. M. D. Schuster, E. J. Power and A. V. Wieder of this office on February 21-24, 1980. It also refers to the discussion of our inspection findings held by the inspectors with R. Purcell and members of his staff on February 23 and 24, 1980.

The inspection included examination of activities related to physical protection against industrial sabotage and against theft of special nuclear material in accordance with applicable requirements of Title 10, Code of Federal Regulations, Part 73, "Physical Protection of Plants and Materials," your Security Plan, and license conditions pertaining to physical protection as described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and records, interviews with facility personnel and observations by the inspectors.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of the findings of your safeguards and security measures are exempt from public disclosure; therefore, the enclosed inspection report will not be placed in the Public Document Room.

MAR 1 0 1980

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

for LeRoy R. Norderhaug, Chief Safeguards Branch

Enclosure: Inspection Report No. 70-1257/80-03 (IE-V-375)

cc w/enclosure: R. Purcell, Manager Auxiliary Operations