## APPETDIX A

## NOTICE OF VIOLATION

Georgia Power Company Hatch 1 and 2 License Nos. DPR-57 NPF-5

Based on the NRC inspection January 28 through January 31, 1980, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Technical Specification Tables 4.1-1 (item 3) and 4.2-7 (item 2), the Intermediate Range Monitors (IRM) are to be functionally tested in order to assure operability. As described by Technical Specification, Section 1.0, Definitions, a channel functional test injects a simulated signal into the channel sensor to verify channel operability including alarm and/or trip functions and channel failure trips.

Contrary to the above, IRM channels are not being functionally tested to assure operability of all alarms, trips and indications from the sensor to panel H11-P603 in the control room.

This is an infraction.