AE

SE 40 05 090 275 bcc to DAC: AUTOCENTRAL FILES
PDR: HQ
LPDR
THC
NSIC
STATE

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000 February 12, 1980

1-020-11

Mr. K. V. Seyfrit, Director Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Subject: Arkansas Nuclear One-Unit 1

Docket No. 50-313 License No. DPR-51

Subject: IE Bulletin 79-14

(File: 1510)

Gentlemen:

By letter dated November 27, 1979, you were informed that following pipe stress analysis of ANO-1 "accessible piping" per IE Bulletin 79-14, reanalysis of pipe support loads revealed some loads to be in excess of those shown on the support drawings. Although an initial engineering evaluation revealed no inoperable supports, we committed to provide you with the results of more extensive analytic evaluations by February 9, 1980.

A recent outage of ANO-1, however, has provided us the opportunity to work on normally inaccessible piping. Due to these efforts the evaluation of support loads for accessible piping has not been completed. ANO-1 has been returned to service and analytical work on accessible piping support loads is now in progress. We plan to provide you with the results of this analysis by April 10, 1980. The results of required analysis for inaccessible piping will also be provided by this date as stated in our letter of January 7, 1980.

Very truly yours,

David C. Trimble

David C. Trimble Manager, Licensing

DCT:DRH:nak

cc: Mr. W. D. Johnson
U.S. Nuclear Regulatory Commission
Post Office Box 2090
Russellville, Arkansas 72801