

jamesbury corp.

8005140207

"Double-Seal"
BALL VALVESWAFER-SPHERE
BUTTERFLY VALVESPNEUMATIC and ELECTRIC
ACTUATORS

April 25, 1980

80-212-000

Mr. B. H. Grier, Director Region I
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Subject: Additional Information to Jamesbury Corp. 10 CFR-21
Notice Dated April 18, 1980

Dear Mr. Grier:

Per my telcon with Mr. McGaughey of the N.R.C. on April 24, 1980 the following additional information is being submitted to better define the problem, its extent and the measures taken and to be taken by Jamesbury Corp.

As you know, on April 16, 1980 Jamesbury was informed by Bechtel Corp. that a ASME Code Class 2, 3" 8226 EX Model A Wafer-sphere valve leaked to atmosphere thru one of the flange bolt holes during pre operational systems testing. Subsequently, Jamesbury has reviewed all Nuclear orders for similar type and size valves. Project Management is contacting the Customers and requesting return of the valves to Jamesbury for re-hydrostatic testing.

The valves are:

<u>Jamesbury Order</u>	<u>Quantity</u>	<u>Customer</u>	<u>Susquehanna</u> Units 1 & 2
NC-21304-03	8*	Bechtel PP&L	
NC-21305-08	8*	Bechtel PP&L	"
NC-40000-01	4*	Bechtel PP&L	"
NC-48856-10	5**	Comm. Ed. Byron	
NC-48856-11	5**	Comm. Ed. Byron	
NC-48857-10	5**	Comm. Ed. Braidwood	
NC-48857-11	5**	Comm. Ed. Braidwood	

* valves installed, but unit not operational

** valves not installed


continued---

In addition, Jamesbury will not ship any 3" 8226 EX Wafer-sphere valves until the cause of this problem is determined and that the appropriate positive corrective actions have been taken and implemented.

If you require any additional information or if I can be of any further assistance, please contact me at (617) 852-0200 extension 2244.

Very truly yours,

JAMESBURY CORP.



F. W. Kreuzinger
Quality Assurance Manager

FWK:hp

cc: Mr. V. Steelo, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555