



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

8005190316
TIC Q

MAR 21 1980

Docket No. 50-331

Iowa Electric Light and Power
Company
ATTN: Mr. Duane Arnold
President
IE Towers
Post Office Box 351
Cedar Rapids, IA 52406

Gentlemen:

This refers to the inspection conducted by Messrs. G. C. Wright and W. F. Christianson of this office on February 19-22, 1980, of activities at the Duane Arnold Energy Center authorized by NRC Operating License No. DPR-49 and to the discussion of our findings with Mr. B. York at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room, except as follows. If the enclosures contain information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt

Iowa Electric Light and
Power Company


- 2 -

MAR 21 1980

of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



R. F. Heishman, Chief
Reactor Operations and
Nuclear Support Branch

Enclosures:

1. Appendix A, Notice
of Violation
2. IE Inspection Report
No. 50-331/80-03

cc w/encl:

Mr. D. Minick, Chief
Engineer
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC