



ARKANSAS POWER & LIGHT COMPANY POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

May 14, 1980

2-050-12

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nucle r Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2

Docket No. 50-368 License No. NPF-6

Licensee Event Report No. 80-020/03L-0

(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning the pressurizer code safety valve (2PSV-4833) that was inoperable during Mode 3 operation.

Very truly yours,

fi David C. Trimble
Manager, Licensing

DCT:GAC:skm

Attachment

cc: Mr. Victor Stello, Jr., Director Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

> Mr. Norman M. Haller, Director Office of Management & Program Analysis U. S. Nuclear Regulatory Commission Washington, D. C. 20555