

March 30, 1980

4327 Alconbury Ln #3  
Houston, Tx. 77021  
(713) 741-4437

J. L. Felton, Director  
Division of Rules and Records  
U. S. Nuclear Regulatory Commission  
Washington D. C. 20585

cc: FOIA REQUEST ATTACHED

Dear Mr. Felton,

Enclosed is an FOIA request, which I am filing in accordance with your letter of March 3, 1980, setting a reduced copying charge, and which was in response to FOIA 80-3, 80-3, and 80-47. To date I have received the package of documents enclosed with that letter.

11 of the 17 requested items are under NRC accession numbers taken from NUREG-0540, Vol. 1 #11, and #12. I have included where possible either the docket number or (in the case of undocketed items) the classification code used by NUREG-0540. I trust this will make finding these easy.

Sincerely,  
*John F. Doherty*  
John F. Doherty

8005220 495

1 - 7912180304 - chrt 5-215 report of crack in low pressure  
turbo. L111, (1 page)

R&T - Research and Technical Assistance Reports

2. 7912140427 Undocketed. Provides information that cracks in pressure vessels do not go through it (4 pages)
3. 7912140475 RIL 010 Results on completed eval of probability of pressure transients in PWRs ( 4 pages)
4. 7912140509 Undocketed. RIL-015, transmits info re: BWR nozzle corner cracks. (4 pages)

TOPREP - Vendor Reports and Related Correspondance

5. 7912190639 Undocketed. Exxon review of NUREG-0630, "Clad Swelling and Rupture for LOCA analysis.
  6. 7912270546 Undocketed. Discusses fuel pellet/clad interaction analysis in response to NRC request.
  7. 7912310188 Undocketed. Initiates new generic task on water shields for sensitive electrical equipment (6 pages)
- \*\*\*\*\*

10CFR Commission Meeting Records

8. 7911210433 Undocketed. Transcript of 11/2/79 meeting in Washington D. C. with regard to fuel cladding swelling (79 pages)
9. 7911200079 Undocketed. Summary of June 2, 1979 meeting on risk assessment and BWR piping (20 pages)

NUREG- Nuclear reports and related correspondance

10. 7908130280 Response to Yellin report by Muller, D R (NRC) 2 pages
11. 7903130284 Response to Muller response by Yellin 2 pages

RES Research and Technical Assistance Repts

12. 7911020173 "Radiation Streaming Study, monthly progress Rep. (5 pages)
13. 7911090315 "State of the Art Literature Review of Water Hammer" (115 pages)
14. 7911210423 LOFT Zircaloy Clad Deformation test interim rep. (20 pgs)

TOPREP Vendor Reports and Related Correspondance

15. 79100554 Eval of effects of Corrosion Particles on Control Rod Drive operation (45 pages)
16. 7911130324 Request for approval of square-root-sum-of-squares for containment dynamic loads. (7 pages)
17. 7911150012 Forwards data on rupture and assembly blockage (4 pages)