



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000  
May 21, 1980

1-050-09

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 1  
Docket No. 50-313  
License No. DPR-51  
Licensee Event Report No. 78-019/01X-1  
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.1, attached is the subject report concerning weld filler wire suspected of being unknowingly mixed by the Nuclear Steam System Supplier (NSSS). This report is an update of a previous report submitted August 18, 1978.

Very truly yours,

David C. Trimble  
Manager, Licensing

DCT:GAC:ms

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Norman M. Haller, Director  
Office of Management and  
Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, D. C. 20555

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES