



72

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

May 6, 1980


Docket No. 40-03392

Allied Chemical Corporation  
Nuclear Chemical Corporation  
ATTN: Radiation Safety Officer  
P. O. Box 8005 R  
Morristown, New Jersey 07906

Gentlemen:

Enclosed is IE Information Notice No. 80-19, "NIOSH Recall of Recirculating-Mode (Closed-Circuit) Self-Contained Breathing Apparatus (Rebreather)," which addresses the NIOSH "stop-sales-and-recall" order to the manufacturers of the BioPak 60P rebreather respirator. Should you have any questions related to the enclosed authorization or guidance, please contact this office.

Sincerely,

  
Boyce H. Grier  
Director

Enclosures:

1. IE Information Notice No. 80-19
2. List of Recently Issued IE Information Notices

CONTACT: P. Knapp  
(215-337-5291)

8005290161

ENCLOSURE 1

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

SSINS: 6870  
Accession No.:  
8002280674

*Dupe.*

IE Information No. 80-19  
Date: May 6, 1980  
Page 1 of 1

NIOSH RECALL OF RECIRCULATING-MODE (CLOSED CIRCUIT) SELF-CONTAINED BREATHING APPARATUS (REBREATHER)

The NRC has been informed by the National Institute for Occupational Safety and Health (NIOSH), the agency that tests and certifies respirators, that some of the NIOSH-certified respiratory protective equipment that NRC licensees use might have been modified by the manufacturer without approval by NIOSH. NIOSH considers such modified equipment not to be certified, even though it might bear their test and certification label.

The equipment in question is the BioPak 30P and 60P, NIOSH test-and-certification numbers TC-13F-84 and TC-13F-85, respectively. The BioPak 30P and 60P are respectively 30-minute and 60-minute, closed-circuit, recirculating-mode, self-contained breathing apparatuses (rebreathers), manufactured by BioMarine Industries, Inc. Our information leads us to believe that NRC licensees have purchased only the 60P equipment.

NIOSH has issued a "stop-sales-and-recall" order to the manufacturer for this equipment. Licensees who have such equipment should check with the manufacturer to determine what action to take to assure that their equipment is in certified status.

The manufacturer's address and telephone number are:

BioMarine Industries Inc.  
45 Great Valley Corporate Center  
Malvern, PA 19355

Tel: (215) 647-7200

ENCLOSURE 2

IE Information Notice No. 80-19  
Date: May 6, 1980  
Page 1 of 1

RECENTLY ISSUED IE INFORMATION NOTICES

| Information Notice No. | Subject   | Date Issued | Issued to  |
|------------------------|---|-------------|--|
| 80-10                  | Partial Loss of Non-Nuclear Instrument System Power Supply During Operation                 | 3/7/80      | All Power Reactor Facilities with an Operating License (OL) or Construction Permit (CP)                                      |
| 80-11                  | Generic Problems With ASCO Valves in Nuclear Applications including Fire Protection Systems | 3/14/80     | All Power Reactor Facilities with an OL or CP, Fuel Fabrication and Processing Facilities                                    |
| 80-12                  | Instrument Failure Causes Opening of PORV and Block Valve                                   | 3/31/80     | All Power Reactor Facilities with an OL or CP  |
| 80-13                  | General Electric Type SBM Control Switches - Defective CAM Followers                        | 4/2/80      | All Power Reactor Facilities with an OL or CP  |
| 80-14                  | Safety Suggestions from Employees   | 4/2/80      | All Power Reactor Facilities with an OL or CP, Fuel Fabrication and Processing Facilities and Materials Priority 1 Licensees |
| 80-15                  | Axial (Longitudinal) Oriented Cracking in Piping  | 4/21/80     | All Power Reactor Facilities with an OL or CP  |
| 80-16                  | Shaft Seal Packing Causes Binding in Main Steam Swing Check and Isolation Valves            | 5/5/80      | All Power Reactor Facilities with an OL or CP  |
| 80-17                  | Potential Hazards Associated With Interchangeable Parts On Radiographic Equipment           | 5/5/80      | All Radiographic Licensees   |
| 80-18                  | Possible Weapons Smuggling Pouch  | 5/5/80      | All Power Reactor Facilities with an OL, Fuel Fabrication and Processing Facilities and Materials Priority I Licensees       |