

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-5001

SHIELDS L. DALTROFF
VICE PRESIDENT
ELECTRIC PRODUCTION

May 27, 1980

Mr. Thomas A. Ippolito, Chief
Operating Reactors Branch #3
Division of Operating Reactors
US Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr. Ippolito:

Your letter of April 25, 1980, on the "Effect of a DC Power Supply Failure on ECCS Performance" requests a schedule for confirmation of a General Electric Company generic study on this subject. In addition, a list of the ECCS equipment that would be available for large and small recirculation loop discharge breaks and recirculation loop suction breaks is needed. This list should take into account both DC power supply failure and loss of equipment due to water spillage.

Our response addressing all of the items requested in your letter will be submitted by August 15, 1980.

Very truly yours,



Acc
7/10

8005300409