

National Valve and Manufacturing Company
Johnstown Plant
Docket No. 99900710/80-01

NOTICE OF VIOLATION

Based on the results of a NRC inspection conducted on March 10-13, 1980, it appears that certain of your activities were not conducted in full compliance with NRC requirements as indicated below:

Section 21.6 of 10 CFR Part 21 requires that corporations subject to these regulations post in a conspicuous position the regulations in this part, Section 206 of the Energy Reorganization Act of 1974 and procedures adopted pursuant to the regulations in this part. If posting of the regulations or procedures is not practicable, a notice describing the regulations/procedures, including the name of the individual to whom reports may be made and location where the regulations/procedures may be examined, can be substituted.

Contrary to the above, neither Section 206 of the Energy Reorganization Act and procedures, or the permitted substitute notice, were posted at the Johnstown plant.

This is a deficiency.