

TEEA



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

MAY 22 1980

Generic Task No. A-10

The Honorable John D. Dingell
Chairman, Subcommittee on Energy
and Power
Committee on Interstate and Foreign Commerce
United States House of Representatives
Washington, D. C. 20515

Dear Mr. Chairman:

Enclosed for the information of the Subcommittee on Energy and Power is the "For Comment" edition of NUREG-0619, "BWR Feedwater Nozzle and Control Rod Drive Return Line Nozzle Cracking". This report provides the staff's resolution of the NRC's Generic Technical Activity A-10, which had been declared an "Unresolved Safety Issue" pursuant to Section 210 of the Energy Reorganization Act of 1974. NUREG-0619 describes the technical issues, the technical studies and analyses performed by the General Electric Company and the NRC staff, the staff's technical positions based on these studies, and the staff's plans for continued implementation of its technical positions.

We intend to issue NUREG-0619 for a 60 day public comment period. Also enclosed for your information is a Federal Register Notice we have issued on this matter.

Sincerely,

Harold R. Denton, Director
Office of Nuclear Reactor Regulation

Enclosures:

- 1. NUREG-0619
- 2. Federal Register Notice

cc: The Honorable Clarence J. Brown