



# New England Memorial Hospital

Formerly NEW ENGLAND SANITARIUM AND HOSPITAL

FIVE WOODLAND ROAD • • STONEHAM, MASSACHUSETTS • 02180 • • (617) 665-1740


May 9, 1980

Hilbert W. Crocker, Acting Chief  
Materials Radiological Protection Section  
U. S. Nuclear Regulatory Commission, Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406 License #20-06006-02

Dear Sir:

In regard to your letter of April 25, 1980, Docket #30-1881, Inspection No. 30-1881/80-01 of 25 March, 1980, and the Notice of Violation (Appendix A of your letter) which was found on the day of inspection, that we were not checking our dose calibrator daily with a cobalt-57 standard, as of that day personnel were instructed that they are required to check the dose calibrator daily with the cobalt-57 standard. This has been accomplished on an ongoing basis and we feel that we have corrected this notice of violation as of that day, 25 March, 1980. I have been checking with the responsible personnel to see that this is accomplished on a daily basis.

Sincerely,

  
J. Blain Boyd, N.M.T. (ASCP)  
Chief of Nuclear Medicine

JBB:al

Copy to U. S. Nuclear Regulatory Commission  
Document Management Branch

Edward L. Wall, Administrator  
Landon Kite, Assoc. Administrator

*No X  
5/10*

8006120399