## Appendix A

## NOTICE OF VIOLATION

Commonwealth Edison Company

Docket Nos. 50-237

50-249

Based on the inspection conducted on March 3 through April 4, 1980, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. This item is an infraction.

Unit 2 and Unit 3 Technical Specifications, Section 6.2.B require that radiation control procedures be maintained, made available to all station personnel, and adhered to. Station Radiation Control Procedure 37-1-A-1, requires that each person read, understand, and adher to the provisions of Special Work Permits (SWP's).

Contrary to the above, during routine tours of the Unit 2 core spray/LPCI corner rooms on March 6, 1980, and the Unit 2/3 refueling floor on March 28, 1980, the inspector observed personnel in controlled, contaminated areas not wearing all of the protective clothing required by the applicable SWP.