

UNITED STATES NUCLEAR REGULATORY COMMISSION  
NOTICE OF EXTENSION OF OPPORTUNITY  
TO FILE REQUEST FOR HEARING  
CONCERNING ISSUANCE OF A SPECIAL NUCLEAR MATERIAL LICENSE  
FOR THE ALABAMA NUCLEAR FUEL FABRICATION PLANT (ANFFP),  
WESTINGHOUSE ELECTRIC CORPORATION,  
TO BE LOCATED NEAR PRATTVILLE, ALABAMA  
DOCKET NO. 70-2909

Agency: U.S. Nuclear Regulatory Commission, Division of Fuel Cycle and  
Material Safety

Action: Notice of Extension to June 14, 1980, of Opportunity to File  
Request for Hearing

Notice has previously been given (March 6, 1980, 45 FR 14724)  
that Westinghouse Electric Corporation has submitted an application for  
a Special Nuclear Material license authorizing Westinghouse to acquire,  
deliver, receive, possess, use and initially transfer special nuclear  
material, for its Nuclear Fuel Division, Alabama Nuclear Fuel Fabrication  
Plant (ANFFP), a new facility proposed for location near Prattville,  
Alabama. The Federal Register notice cited above further stated that  
persons who wished to file a request for hearing should do so by April  
7, 1980.

The March 6, 1980, Federal Register notice also stated that the  
applicant's Environmental Report and supplements thereto would be


8006190745

provided to the State Clearinghouse, Alabama Development Office, c/o State Capitol, Montgomery, Alabama 36130; and the Metropolitan Clearinghouse, Central Alabama Regional Planning and Development Commission, 808 Lawrence Street, Montgomery, Alabama 36104. Because these documents did not arrive in sufficient time for review, the deadline for filing petitions requesting a hearing has been extended to June 14, 1980.

Questions should be directed to W. T. Crow, U.S. Nuclear Regulatory Commission, Division of Fuel Cycle and Material Safety, 396-SS, Washington, D.C. 20555, Phone (301) 427-4510.

Dated at Silver Spring, Maryland this 3rd day of April, 1980.

FOR THE NUCLEAR REGULATORY COMMISSION

  
R. G. Page, Acting Chief  
Uranium Fuel Licensing Branch  
Division of Fuel Cycle and  
Material Safety