

ATTACHED IS A PART 21 REPORT FROM IE MAIL UNIT - ROOM 359E/W

PART 21 IDENTIFICATION NO. 79-110-004 COMPANY NAME Tube Turns Inc

DATE OF LETTER 6/6/80 DOCKET NO. _____

DATE DISTRIBUTED 6/12/80 ORIGINAL REPORT SUPPLEMENTARY

DISTRIBUTION:

REACTOR(P)

FUEL CYCLE &

SAFEGUARDS(S)

MATERIALS(M)

NRR/DOR, DIRECTOR (2)

AD/FFMSI

AD/SG-IE

NRR/DPM DIRECTOR (2)

NMSS/FCMS

AD/ROI

AD/ROI (2)

REGIONS

REGIONS

AD/RCI

IE FILES

NRR/DOR, DIRECTOR

REGIONS

PDR

NMSS/SG SS-881

IE FILES

LPDR

PDR

CENTRAL FILES

CENTRAL FILES-SS-396

LPDR

CENTRAL FILES (CHRON)

CENTRAL FILES(CHRON)
(016)

TERA

PDR

TERA

IE FILES (2)

LPDR

LOEB/MPA MNB 5715

CENTRAL FILES 016

TERA

AEOD - MNB-7602

CENTRAL FILES (CHRON)

LOEB/MPA MNB 5715

CENTRAL FILES - SS-396

AEOD MNB-7602

LOEB/MPA MNB 5715

AEOD MNB-7602

ACTION:

PRELIMINARY EVALUATION OF THE ATTACHED REPORT INDICATES LEAD RESPONSIBILITY FOR FOLLOW-UP AS SHOWN BELOW:

IE

NRR

NMSS

OTHER

RCI

ROI
SG
FFMSI

8006200024

REV.



Tube Turns Division

CHEMETRON CORPORATION
Box 32160, Louisville, Kentucky 40232
Telephone 502 774-6011

50-200

June 6, 1980

79-110-004

U. S. Nuclear Regulatory Commission
Director, Office of Inspection and Enforcement
Washington, D. C. 20555

Gentlemen:

Our letters of April 12, 1979, May 10, 1979, and January 15, 1980, reported to you regarding the mixed heat of steel furnished by U. S. Steel to Tube Turns from which we manufactured 4" elbows and 2" tees to the requirement of A234WPB.

Following is a report on the status of the investigation of fittings at the listed Nuclear Power Stations.

The investigations at the following Nuclear Power Stations have been closed as a result of investigations and testing performed at the site.

Brunswick	Prairie Island	Midland
Cherokee	Shoreham	Bellefonte
Joseph M. Farley	Waterford III	Brown's Ferry
Nine Mile Island #2	Wm. H. Zimmer	Hartsville
North Anna II	LaSalle	Phipps Bend
*Palo Verde	Limerick	Sequoyah
*San Onofre	*Grand Gulf	Yellow Creek

We are awaiting written confirmation from those indicated by an asterisk that their investigations are complete. They have advised by phone that they have closed their files.

In view of the above, we are considering this our final report on this subject.

Very truly yours,

J. L. Seay
J. L. Seay
Manager-Quality

/dmt

Tube Turns Division

CHEMETRON CORPORATION

U. S. Nuclear Regulatory Commission -2-

6/6/80

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

U. S. Nuclear Regulatory Commission
Region II
Suite 3100
101 Marretta St. N. W.
Atlanta, Ga. 30303