

DCD/DCB

DKN 3001614

DKN 3008938

OCT 30 1989

Reid Memorial Hospital  
ATTN: Mr. T. Sobol  
Senior Vice President  
1401 Chester Blvd.  
Richmond, IN 47374

Licenses No. 13-03284-02; 13-03284-03

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. P. Reichhold of this office on September 19, 1989, of activities authorized by NRC Byproduct Material Licenses No. 13-03284-02 and No. 13-03284-03 and to the discussion of our findings with John Spellmeyer, M.D. on October 18, 1989.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

There were no violations of NRC requirements found during the inspection of License No. 13-03284-02 (nuclear medicine). However, during the inspection of License No. 13-03284-03 (cobalt-60 teletherapy unit), certain of your activities appear to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski, Chief  
Nuclear Materials Safety  
Section 1

Enclosure: Notice of Violation

cc w/enclosure:  
DCD/DCB(RIDS)

RIII RIII  
Reichhold/gd Sreniawski

yes 10/27/89 yes

8911070050 891030  
REG3 LIC30  
13-03284-02 PNU

IE07