SOUTHERN CLAY

A DIVISION OF Ellipsical Forum INDUSTRIES, INC.

Rie. File

Mr. R. S. Caniano U.S. Nuclear Regulation Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

Ref: License No. 24-18735-01

Dear Mr. Caniano:

Action has been taken to rectify the regulatory concerns stated in your letter of October 13, 1989. The actions taken are:

- Return of our rate count meter to the manufacturer for calibration.
- Generation of an inventory form, for our licensed material, which will be kept in my files. This form will also contain information concerning the calibration date of the rate count meter.

If you have any questions concerning this matter you may contact me at (314) 545-3555.

Singerely

Henry Y. Simpson Electrical Engineer

HYS/dku

8911150123 891023 REG3 LIC30 24-18735-01 PDC TEO7