DCD/DCB

NOV 9 1989

Deket 30-29624

License No. 21-23662-01E

A.in. Couglas E. Patton 24777 Denso Drive Southfield, MI 48086-5133

Gentlemen:

This refers to the routine safety inspection conducted by J. W. Patterson of this office on October 23, 1989, of activities authorized by NRC Byproduct Material License No. 21-23662-01E and to the discussion of our findings with you and a member of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Roy J. Caniano, Chief Nuclear Materials Safety Section 2

TEC

Enclosure: Notice of Violation

cc w/enclosure: DCD/DCB (RIDS)

RIII Patterson/gd Canlano 11/3/89

8911160176 891109 R503 L1030 21-23662-01F PNU