

Portland General Electric Company Trojan Nuclear Plant 71760 Columbia River Hwy Rainier, Oregon 97048 (503) 556-3713 October 19, 1989 CPY-265-89

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Gentlemen:

Special Report

Limiting Condition for Operation (LCO) 3.7.8.1 of the Trojan Technical Specifications (TTS) requires submittal of a Special Report if one fire pump is inoperable for greater than 7 days.

The diesel fire pump was declared inoperable on September 27, 1989. A fire engine, from the local municipality, was staged onsite to provide for the loss of redundancy of the diesel fire pump.

The pump was returned to service on October 13, 1989.

Sincerely,

c. F. Yundt

General Manager Trojan Nuclear Plant

CPY DWS JWL/RQR/TRB: ses

c: Mr. David Stewart-Smith State of Oregon Department of Energy

> Mr. John B. Martin Regional Administrator US Nuclear Regulatory Commission

Mr. R. Barr USNRC Resident Inspector Trojan Nuclear Plant

Distribution