



DCD/DCB

August 28, 1989

United States  
Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60317

Attn: R.J. Caniano, Chief  
Nuclear Materials Supply  
Section 1

Re: License No. 21-24565-01

03030413

This is our written response regarding the safety inspection conducted on June 27, 1989 by Ms. T.L. Simmons.

In regards to license condition no. 14, on all packages containing radioactive material. We have begun stamping the outside and inside of the packages with a stamp stating: "This package conforms to the conditions and limitations specified in 49 CFR 173.421 for excepted radioactive material, limited quantity, n.o.s., UN2910".

In regards to violation of item no 8, the individual who is responsible for redistribution of invitro kits has been instructed by the radiation safety officer on the emergency procedures and radiation safety practices.

As of the above date, full compliance has been achieved.

Sincerely,

Tariq L. Baig  
President

TLB/pjl

SEP 11 1989

8910260132 890828  
REG3 LIC30  
21-24565-01 PNU

ZE07

10