SAFETY INSPECTION			
NAVAL DENTAL RESEARCH INSTITUTE NAVAL TRAINIUG CENTER GREAT LAKES, IL GOOST - 5259		U.S. NUCLEAR REGULATOR: COMPISSION REGION III 799 ROOSEVELT ROAD GLEN FLLYN, IL 60137	
3. DOCKET NUMBER(S)	4. LICENSE NUMBERIS		S. DATE OF INSPECTION
None	12-6578	16-41NP	5 SEPTEMBER 1989
Licensee			
The inspection was an examination of the act Regulatory Commission's (NRC) rules and reg and representative records, interviews, with p	ul. ans and the conditions of yo	ir license. The inspection	ion sefety and to compliance with the Nuclear consisted of selective examinations of procedures s a result of this inspection are as follows:
1. Within the scape of this inspection, no	violations were observed.		
2. The inspector also verified the steps you those actions at this time.	ou have taken to correct the violation	ions identified during the	last inspection. We have no further questions on
3. During this inspect on certain of your THIS IS A NOTICE OF VIOLATION	activities, as checked below, were which is required to be posted in	in violation of NRC requi accordance with 10 CFR	rements. 19.11.
·			was not properly posted to indicate the presence
L_J^ot•			10 CFR 20.203(b), (c), (d), (e) or 34.42.
R. Containers located in	radioactive material, 10 CFR 20	203(f)(1), or (f)(2).	of sealed sources were not performed at the proper
D. Records of 10 CFR  E. Documents were not properly post			were not properly maintained.
F. Reports or notifications of		or License Condition Nur	mber were not made in accordance /
B910310270 B9 REG2 LIC30 REG2 LIC30 REG2 LIC30	1012 PNII		
I hereby state that within 30 days the action This statement of corrective actions is made the NRC.	s described by me to the inspecto in accordance with the requireme	r will be taken to correct to the of 10 CFR 2.201. No	the violations identified in the items checked above, further response will be submitted unless required by
Cleville - LICENSEE	9/5/89	W. SIGNATUR	Kuddaly 5 Sept max/