NRC Form 591 (12-81)			U.S. NUCLEAR REGULATORY COMMISSION
10 CFR 2.201	SAFETY I	NSPECTION	
1. LICENSEE		2. REGIONAL OF	FICE
National Mines Corporation P. O. Box 12022 Lexington, KY 40579		U. S. Nuclear Regulatory Commission Suite 2900 101 Marietta Street, N.W.	
contrageout in toors	Way and and	Atlanta,	GA 30323
3. DOCKET NUMBER (S)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTION
030-20663	16-21437-01		8-14-89
<ul> <li>and representative records, interviews, with personal sector and the scope of this inspection, no vio</li> <li>2. The inspector also verified the steps you have actions at this time.</li> <li>3. During this inspection certain of your actions that it is a notice of violation who is a sector of the steps with the steps and the steps are sector as a sector of the steps and the steps with the steps are sector as a sec</li></ul>	annel, and observations by the lations were observad. neve taken to correct the violat vities, as checked below, were ich is required to be posted in i	inspector. The find ions identified durin in violation of NRC accordance with 10	requirements. CFR 19.11. was not properly posted to indicate the presence
C	lenk tests of Teo	or License Condition	IN 11/86 \$ 5/89 were not properly maintained.
F. Reports or notifications of			were not made in accordance
With 10 CFR	······································	ar License Condition	
B911060231 B REG2 LIC30 16-21437-01			
I hereby state that within 30 days the actions day This statement of corrective actions is made in ac the NRC.	scribed by me to the inspector coordance with the requirement	will be taken to cor ts of 10 CFR 2.201.	Pect the violations identified in the items checked above. No further response will be submitted unless required by DB TReis 8/14/89