

NORTHEAST UTILITIES



THE CONNECTICUT LIGHT AND POWER COMPANY
WESTERN MASSACHUSETTS ELECTRIC COMPANY
NEW YORK WATER POWER COMPANY
NORTHEAST UTILITIES SERVICE COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY

General Offices • Seiden Street, Berlin, Connecticut

P.O. BOX 270
HARTFORD, CONNECTICUT 06141-0270
(203) 665-5000

October 24, 1989

Docket Nos. 50-213

50-245

50-335

50-423

B13392

Re: Bulletin 88-10,
Supplement 1

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

Gentlemen:

Haddam Neck Plant
Millstone Nuclear Power Station, Unit Nos. 1, 2, and 3
NRC Bulletin 88-10, Supplement 1

NRC Bulletin 88-10⁽¹⁾ was issued on November 22, 1988, to request that addressees take actions to provide reasonable assurance that molded-case circuit breakers purchased for use in safety-related applications perform their safety functions. In addition, the bulletin required that addressees submit certain information to the NRC regarding circuit breakers that could not be traced to the circuit breaker manufacturer.

Supplement 1 to NRC Bulletin 88-10⁽²⁾ required that addressees:

1. Review written reports submitted to the NRC in accordance with Bulletin 88-10 and verify that the responses meet the bulletin provisions as clarified by this supplement.
2. Prepare and retain documentation for possible audit that indicates that Item 1 of the actions requested has been performed as requested.

The purpose of this letter is to confirm that the Connecticut Yankee Atomic Power Company (CYAPCO) and Northeast Nuclear Energy Company (NNECO) have

(1) C. E. Rossi letter to All Licensees, "NRC Bulletin 88-10: Nonconforming Molded-Case Circuit Breakers," dated November 22, 1988.

(2) C. E. Rossi letter to All Licensees, "NRC Bulletin 88-10, Supplement 1," dated August 3, 1989.

8911060310 891024
PDR ADDCK 05000213
Q PNU

IF21
40


U.S. Nuclear Regulatory Commission
B13392/Page 2
October 24, 1989

reviewed their submittals⁽³⁾⁽⁴⁾ regarding NRC Bulletin 88-10 for the Haddam Neck Plant and Millstone Unit Nos. 1, 2, and 3, respectively, and have concluded that these responses meet the Bulletin provisions as clarified by the August 3, 1989, supplement.

Please feel free to contact us if you have any questions.

Very truly yours,

CONNECTICUT YANKEE ATOMIC POWER COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY



E. J. Mroczka
Senior Vice President

cc: W. T. Russell, Region I Administrator
M. L. Boyle, NRC Project Manager, Millstone Unit No. 1
G. S. Vissing, NRC Project Manager, Millstone Unit No. 2
D. H. Jaffe, NRC Project Manager, Millstone Unit No. 3
A. B. Wang, NRC Project Manager, Haddam Neck Plant
W. J. Raymond, Senior Resident Inspector, Millstone Unit Nos. 1, 2, and 3
J. T. Shedlosky, Senior Resident Inspector, Haddam Neck Plant

(3) E. J. Mroczka letter to U.S. Nuclear Regulatory Commission, "NRC Bulletin 88-10," dated March 16, 1989.

(4) E. J. Mroczka letter to U.S. Nuclear Regulatory Commission, "NRC Bulletin 88-10," dated June 16, 1989.