U.S. NUCLEAR REGULATORY COMMISSION

NAC Form 591 (12-81) 10 CFR 2.C.FF

SAFETY INSPECTION

1. LICENSEE

Wanpaca Foundry, Inc PO BOX 249 Wanpaca, Wi, 54981

Kennett E. Elandt 10-12-89

2. REGIONAL OFFICE

U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137

3. DOCKET NUMBER(S)

4. LICENSE NUMBER(S)

15. DATE OF INSPECTION

03008461	48-15031-01	10-12-89
Licensee:		
Regulatory Commissions (NRC) rules an	nd regulations and the conditions of your license. The	late to radiation safety and to compliance with the Nuclear he inspection consisted of selective examinations of procedures the findings as a result of this inspection are as follows:
1. Within the scope of this inspectio	n, no violations were observed.	
2. The inspector also verified the ste those actions at this time.	ps you have taken to correct the violations identifie	ed during the last inspection. We have no further questions on
7. During this inspection certain of	your activities, as checked below, were in violation of	of NPC requirements
	TION which is required to be posted in accordance w	
		was not properly posted to indicate the presence
B. Containers located in		were not properly
	ce of radioactive material. 10 CFR 20.203(f)(1), or	
		of sealed sources were not performed at the proper
frequencies. 10 CFR		License Condition Number
D. Records of LM1'C MZ		were not properly maintained.
10 CFR	or License Co	ondition Number
E. Documents were not properly	posted or otherwise made evailable. 10 CFR 19.11	
F Reports or notifications of		were not made in accordance
	or Licer * Co	
		Profesional Company of the Company o
— costa	70049 891012	
REG3	LIC30 031-01 PDC	
48-15	031-01	
Гк		
I hereby state that within 30 days the ac This statement of corrective actions is m	tions described by me to the inspector will be taken ade in accordance with the requirements of 10 CFR	to correct the violations identified in the Items checked above. 2.201. No further response will be submitted unless required by
the NRC.		