

October 2, 1989

U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

Gentlemen:

This will advise you of a possible future 10CFR 21 report in regard to activation energy and ampacity values applicable to Rockbestos silicone rubber insulated cables.

The potential safety hazard would be a reduction in qualified life if it should be found necessary to revise these values significantly.

We are currently investigating this matter and if it is determined that a reportable problem exists we will proceed in accordance with the requirements of 10 CFR 21.

Very truly yours,

131 Littlatus

Quality Assurance Manager

GGL/saw

8911080254 891002 PDR PT21 EMVROCK PNU 1910