NOV - 1 1989

In Reply Refer To: Docket: 50-382/89-24

Louisiana Power & Light Company
ATTN: J. G. Dewease, Senior Vice President
Nuclear Operations
317 Baronne Street
New Orleans, Louisiana 70160

Gentlemen:

This refers to the team inspection conducted by Mr. Nemen M. Terc of this office and other accompanying personnel during the period August 29 through September 1, 1989, of activities authorized by NRC Operating License NPF-38 for Waterford-3, and to the discussion of our findings with you and other members of your staff at the conclusion of the inspection.

Areas examined during the inspection included the implementation of the emergency plan and procedures during the annual emergency response exercise. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspection team. The inspection findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

The enclosed report identified four exercise weaknesses in your emergency preparedness program. Weaknesses involved: a delay in notifying the NRC; a degraded flow of information between the control room and the technical support center (TSC); an instance of lack of technical support from the TSC to dose assessors; and an instance of lack of adequate coordination of in-plant repair teams by the operational support center.

Exercise weaknesses according to 10 CFR Part 50, Appendix E.IV.F.5, are inspection findings that need to be corrected by the licensee. You are requested to provide this office with a description of your corrective measures and your schedule for completing these actions within 30 days after receipt of this letter.

We have also examined actions you have taken with regard to previously identified inspection findings. The status of these items is identified in paragraph 2 of the enclosed report.

NM SEPS

C: SEPSOP DAPowers 10/24/89 D: DRSS D: DRP
ABBeach O O Julinoan
10/50/89

8911130243 691101 PDR ADOCK 05000382 TE35

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely.

Guynn, Goz:

James L. Milhoan, Director

Division of Reactor Projects

Enclosure: Appendix - NRC Inspection Report 50-382/89-24

cc w/enclosure: Louisiana Power & Light Company ATTN: R. P. Barkhurst, Vice President Nuclear Operations P.O. Box B Killona, Louisiana 70066

Louisiana Power & Light Company ATTN: J. R. McGaha, Jr., Plant Manager P.O. Box B Killona, Louisiana 70066

Louisiana Power & Light Company ATTN: L. W. Laughlin, Site Licensing Support Supervisor P.O. Box B Killona, Louisiana 70066

Louisiana Power & Light Company ATTN: G. M. Davis, Manager, Events Analysis Reporting & Response P.O. Box B Killona, Louisiana 70066

Monroe & Leman ATTN: W. Malcolm Stevenson, Esq. 201 St. Charles Avenue, Suite 3300 New Orleans, Louisiana 70170-3300

Shaw, Pittman, Potts & Trowbridge ATTN: Mr. E. Blake 2300 N Street, NW Washington, D.C. 20037 U.S. Nuclear Regulatory Commission ATTN: Resident Inspector P.O. Box 822 Killona, Louisiana 70066

Middle South Services, Inc. ATTN: Ralph T. Lally, Manager of Quality Assurance P.O. Box 61000 New Orleans, Louisiana 70161

Chairman Louisiana Public Service Commission One American Place, Suite 1630 Baton Rouge, Louisiana 70825-1697

Louisiana Power & Light Company ATTN: R. F. Burski, Manager, Nuclear Safety and Regulatory Affairs 317 Baronne Street New Orleans, Louisiana 70112

U.S. Nuclear Regulatory Commission ATTN: Regional Administrator, Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Office of Environmental Affairs ATTN: William H. Spell, Administrator Nuclear Energy Division P.O. Box 14690 Baton Rouge, Louisiana 70898

President, Police Jury St. Charles Parish Hahnville, Louisiana 70057

Mr. William A. Cross Bethesda Licensing Office 3 Metro Center Suite 610 Bethesda, Maryland 20814

Chief, Technological Hazards Branch FEMA Region 6 Federal Center 800 North Loop 288 Denton, Texas 76201-3698

bcc to DMB (IE35)

bcc distrib. by RIV:

*RRI

*Section Chief (DRP/A)

*DRSS

*Project Engineer (DRP/A)

*RIV File

*D. Wigginton, NRR Project Manager (MS:

Lisa Shea, RM/ALF

*Inspectors

*C. Hackney

*w/766

*R. D. Martin, RA

*DRP

*MIS System

*RSTS Operator

*DPS

13-D-18)

*Section Chief (SEPS)

*Division Director (DRSS)