IE FILE COPY

TOLEDO

L78-343 FILE: RR 2 (NP-33-78-99)

August 18, 1978

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glan Ellyn, Illinois 60137

Dear Mr. Kepplen:

Reportable Occurrence 78-084 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: July 24, 1978

0

Enclosed are three copies of Licensee Event Report 78-084 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Teng O Mun

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station

TDM/JRL/1jk

Enclosure

cc: Dr. Ernst Volgenau, Director Office of Inspection and Enforcement Encl: 30 copies LER 78-084

> Mr. William G. McDonald, Director Office of Management Information and Program Control Encl: 3 copies LER 78-084



COPY SENT REGION

8001310636

782360107

300 MADISON AVENUE TOLEDO, OHIO 43552

THE TOLEDO EDISON COMPANY EDISON PLACA