

78-10
IE FILE COPY

TOLEDO
EDISON

February 8, 1978

L78-089

Docket No. 50-346
License No. NPF-3

FILE: RR 2 (NP-33-78-12)

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137


18

Dear Mr. Keppler:

Reportable Occurrence 78-010
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: January 15, 1978

Enclosed find three copies of Licensee Event Report 78-010 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,



Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/JRL/ljk

Enclosures

cc: Dr. Ernst Volgenau, Director
Office of Inspection and Enforcement
Encl: 30 copies Licensee Event Report
30 copies Supplemental Information Sheet

Mr. William G. McDonald, Director
Office of Management
Information and Program Control
Encl: 3 copies Licensee Event Report
3 copies Supplemental Information Sheet

~~780470001~~

A002/S
1/11

8002030020