JUL 3 0 1973

50.346

D. J. Skovholt, Assistant Director for OR's, L

QA FOR OPERATIONS

In December 1972, letters were sent to selected licensees, listing deficiencies in their Quality Assurance Program as it applies to operation, maintenance, repair, refueling, and modification. The licensees were asked to reassess their program in light of the deficiencies noted, and Safety Guide No. 33, and resubmit a description responsive to the guide.

Responses have been received from the licensees for the following facilities:

Dresden Yankee Humboldt Bay Big Rock Point Connecticut Yankee Indian Point Oyster Creek Ginna LaCrosse San Onofre Monticello

The facilities listed in my memorandum to you dated November 16, 1972, which are not included above are given below with the reason for their omission:

Quad Cities - Not on original list of March 1971, but included by the Project Manager in communications with the licensee regarding the Dresden Station.

Fermi - No further action necessary due to anticipated shutdown of facility, per Project Manager on 5/18/72.

Peach Bottom 1 - No further action necessary due to anticipated shutdown of facility, per the ORB Technical Coordinator on 12/5/72.

Nine Mile Point - The Quality Assurance Branch accepted the lead review responsibility for this facility in December 1972.

8002030117

OFFICE >	MULLIUM
SURNAME >	
DATE	

Two facilities were added to the review by the ORB Technical Coordinator and their names and status are as follows:

Millstone - The Quality Assurance Branch accepted the lead review responsibility for this facility in December 1972.

Monticello - Operational Safety Branch will complete this review.

Our reviews of the QA for Operations programs of the above facilities have been substantially completed. Except for the two facilities named below, the QA review responsibility for the facilities listed has now been forwarded to the Quality Assurance Branch for final review to assure consistency. (Some duplication of effort has existed between our branch and the Quality Assurance Branch, especially where a utility has submitted an application for a license to operate another reactor, and has addressed the QA Program for Operations in Section 17.2 of the FSAR.)

Two facilities will remain with the Operational Safety Branch: LaCrosse and Monticello. The response from Dairyland Power Cooperative concerning the LaCrosse facility is acceptable. A memo will be sent to you shortly. Additional information has been requested regarding Monticello as stated in our memorandum to you dated July 3, 1973.

Original Signed by Yictor Stello

Victor Stello, Jr., Assistant Director for Reactor Safety Directorate of Licensing

cc:

J. M. Hendrie, L:TR

S. H. Hanauer, DRTA

W. McDonald, L:OPS

T. J. Carter, ORB

R. H. Vollmer, QAB

D. L. Ziemann, ORB-2

R. J. Schemel, ORB-1

R. W. Houston, L:0SB

C. R. VanNiel. OSB

OFFICE >	L:0SB)	L:OSB	-	L:AD/RS		
	CRVanifiel:1kd	RWHaustor	7	vs 2010		
		7/2//73		7/30/73 .		