1 Euran



Docket No. 50-346 License No. NPF-3

August 3, 1977

Serial No. 341

IE FILE COPY

LOWELL E. ROE Vice President Facilities Development (419) 259-5242



Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence NP-33-77-20 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: July 7, 1977

Enclosed find three copies of Licensee Event Report NP-33-77-20 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

LER: 1 jk

Enclosures

cc: Dr. Ernst Volgenau, Director

Office of Inspection and Enforcement

Encl: 30 copies Licensee Event Report

30 copies Supplemental Information Sheet

Mr. William G. McDonald, Director Office of Management Information and Program Control Encl: 3 copies Licensee Event Report 3 copies Supplemental Information Sheet make objet

THE TOLEDO EDISON COMPANY EDISUN PLAZA

300 MADISON AVENUE

TOLEDO, OHIO 43652