Letter from Florida Power Corporation, J. T. Rodgers, OCT 18 1973 dated October 16, 1973 - 50-302/73-7, 50-302/73-8 and 50-302/73-9

DISTRIBUTION:
H. D. Thornburg

RO:HQ (5)

DR Central Files

Regulatory Standards(3)

Directorate of Licensing (13)


J. R. Lundy, L

PDR Local PDR NSIC OIS, OR State

PINTER CONLINEDE

04 CI NA 61 TOD CTR

RECEIVED



UNITED STATES ATOMIC ENERGY COMMISSION

DIRECTORATE OF REGULATORY OPERATIONS REGION II - SUITE 818 230 PEACHTREE STREET, NORTHWEST ATLANTA, GEORGIA 30303

TELEPHONE: (404) 828-4503

RO Inspection Report No. 50-302/73-9

Licensee: Florida Power Corporation

3201 34th Street South

P. O. Box 14042

St. Petersburg, Florida 33733

Facility Name: Crystal River 3

Docket No.:

50-302

License No.:

CPPR-51

Category:

B1

Location: Crystal River, Florida

Type of License: B&W, PWR, 2452 Mwt

Type of Inspection: Routine, Announced

Dates of Inspection: September 20-21, 1973

Date of Previous Inspection: September 19, 1973

Principal Inspector: M. S. Kidd, Reactor Inspector

Facilities Test and Startup Branch

Accompanying Inspector: D. J. Burke, Reactor Inspector

Facilities Test and Startup Branch

Other Accompanying Personnel: None

Principal Inspector: (

M. S. Kidd, Reactor Inspector

Facilities Test and Startup Branch

Reviewed By:

C. E. Murphy, Chief

Facilities Test and Startup Branch

SUMMARY OF FINDINGS

I. Enforcement Matters

A. Violations

None

B. Safety Items

None

II. <u>Licensee Action on Previously Identified Enforcement Matters</u>
Not applicable.

III. New Unresolved Items

None

IV. Status of Previously Identified Unresolved Items
Not applicable.

V. Unusual Occurrences

None

VI. Management Interview

A management interview was held at the conclusion of the inspection September 21, 1973. The following licensee personnel attended:

Florida Power Corporation (FPC)

Construction Department

H. L. Bennett - Director, Generation Construction

C. E. Jackson - Crystal River Construction Superintendent

J. C. Hobbs - Superintendent, Mechanical and Electrical Systems

Generation Engineering Department

- P. G. Davis Manager, Power Testing
- J. S. Schuyler Power Test Supervisor
- A. P. Vogt Power Test Supervisor
- D. E. Pedrick Quality Engineer
- R. W. Slater Engineer II, Electrical

Production Department

- J. Alberdi Nuclear Plant Superintendent
- W. P. Stewart Assistant Plant Superintendent

A. Subjects Discussed

The inspectors discussed the manner in which inspections would be conducted during preoperational testing and operations.

The status of construction, test procedures, and the QA program for testing were also discussed. (Details I, paragraphs 3 and 4)

DETAILS I

Prepared By

Reactor Inspector

Facilities Test and Startup Branch

Dates of Inspection: September 20-21, 1973

Reviewed By:

C. E. Murphy, Chief Facilities Test and Startup Branch

1. Personnel Contacted

Same as those identified in the management interview section of the Summary of this report.

2. General

This was the initial Facilities Test and Startup Branch inspection of the Crystal River Unit 3 site. It was made to familiarize the inspectors with the site and to meet licensee personnel. Also, the status of construction, the start of preoperational testing, and the status of the quality assurance (QA) program for testing were reviewed and discussed.

3. Plant Status

Licensee personnel estimate overall construction of Unit 3 to be 82% complete. No significant testing has started; it is estimated that it will begin in approximately two months.

4. OA and Administrative Controls for Testing

The inspector was informed that an independent QA contractor will be employed for the testing program. It is expected that the name of the contractor will be announced within two to three weeks. The contractor will develop implementing QA procedures within the framework of the FPC QA Manual.

The Crystal River Test Program Guide (TPG) defines the administrative controls for preoperational testing. It is currently being revised and is to be reissued in approximately three weeks.

SEP 25 1973

Florida Power Corporation Crystal River 3

RO Inspection Report No. 50-302/73-9

cc w/encl:

H. D. Thornburg, RO

9:HQ (5)

DR Central Files

Regulatory Standards (3)

Directorate of Licensing (13)

cc encl. only:

*PDR

*Local PDR

*NSIC

*DTIE, OR

*State

^{*}To be dispatched at a later date.