



HELPING BUILD ARKANSAS

ARKANSAS POWER & LIGHT COMPANY

8TH AVENUE AND PINE STREET • PINE BLUFF, ARKANSAS 71601 • (501) 534-1330

October 31, 1973

POOR ORIGINAL

Mr. D. F. Knuth
Director of Regulatory Operations
United States Atomic Energy Commission
Washington, D. C. 20545

SUBJECT: ARKANSAS POWER & LIGHT COMPANY
ARKANSAS NUCLEAR ONE - UNIT 1
DOCKET NO. 50-313
INVERTER MALFUNCTION

Dear Mr. Knuth:

On October 1, 1973, Arkansas Power & Light Company informed the Regulatory Operations Office in Atlanta, Georgia of a situation which could be considered reportable under 10 CFR 50.55(e), "Conditions of Construction Permits".

Attached is our report of the incident, including a description of the incident, safety implications, and corrective action taken.

Very truly yours,

J. D. Phillips
J. D. PHILLIPS
Senior Vice President

JDP:NAM:mb

Attachment as noted

cc: Mr. Norman C. Moseley, Director
Directorate of Regulatory Operations
Region II
United States Atomic Energy Commission
230 Peachtree Street, N.W. - Suite 818
Atlanta, Georgia

*W. J. ...
50-313*

3 1122

8004160328

