

done 12/9/67
wde

SUPPLEMENT NO. 14

TABLE OF CONTENTS AND CHANGE DIRECTIONS

<u>SECTION</u>	<u>CONTENTS AND DIRECTIONS</u>	<u>PAGES</u>
1	<u>QUALITY ASSURANCE PROGRAM</u> (Appendix 1-B)	
	Insert these pages behind Appendix 1-A (Tab Sheet 1-B will be sent later.)	1-B-i & ii, 1-B-1 through 1-B-50, Figures 1, 2, 3, Appen- dix B
	In Section 5 of the PSAR insert these pages and remove those they replace	5-47, 5-48
	In Supplement No. 3 to the PSAR insert these pages and remove those they re- place. Delete pages 8.4-9 and 8.5-2.	8.3-1, 8.3-2, 8.4-1, 8.4-2, 8.4-5, 8.4-6, 8.4-7, 8.4-8, 8.5-1
2	<u>SPEN FUEL POOL DESIGN</u>	
	In Supplement No. 6 to the PSAR insert these pages and remove those they re- place.	4, 5
3	<u>REACTOR BUILDING BASE SLAB AND LINER PLATE REVISIONS</u>	
	In Section 5 of the PSAR insert these pages and figures and remove those they replace.	5-1, 5-2, 5-7, 5-8, 5-9, 5-12, Figures 5-2 and 5-3
	In Supplement No. 4 to the PSAR insert these pages and Figure and remove those which they replace. Delete Figures 11.2.3-1 and 11.2.3-1a	11.2.2-1, 11.2.3-1, 11.2.3-2, 11.2.23-1, 11.5.3-1, 11.5.3-2, Figure 11.2.23-1
4	<u>PSAR TABLE OF CONTENTS</u>	
	In the Table of Appendices replace this page.	vii