Rearter Facilities.

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
REGION IV
511 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

. .

April 9 , 1976

Arkansas Power & Light Company ATTN: Mr. J. D. Phillips Senior Vice President Sixth & Pine Streets Pine Bluff, Arkansas 71601 Docket No. 50-313

Gentlemen:

Thank you for your letter of March 29, 1976, in response to our letter and Notice of Violation, dated December 23, 1975. We have no further questions at this time and we will review your corrective actions during a future inspection.

Sincerely,

G. L. Madsen, Chief, Reactor Operations and Nuclear Support Branch

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

bec w/ltr W. Cavanaugh to G. L. Madsen, dtd 3/29/76

IE Chief, FCSEB
IE Chief, APD
IE Chief, TAB
IE:IE Reg. Coord.
IE Files
Central Files
Standards Development
DRL (12)
TIC
NSIC
PDR:HQ
Local PDR
Arkansas State Board of Health