TIC

DAIRYLAND
COOPERATIVE . P.O. BOX 817 . 2615 FAST AV SOUTH . LA CROSSE. WISCONSIN 54601

(608) 788-4000

June 2, 1980

In reply, please refer to LAC-6964

DOCKET NO. 50-409

Mr. James G. Keppler
Regional Director
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE

LA CROSSE BOILING WATER REACTOR (LACBWR) PROVISIONAL OPERATING LICENSE NO. DPR-45 IE BULLETIN NO. 80-07, SUPPLEMENT NO. 1

Reference: (1) NRC Letter, Keppler to Linder,

dated May 14, 1980.

(2) DPC Letter, Linder to Keppler, LAC-6871, dated April 18, 1980.

Dear Mr. Keppler:

Our letter, Reference 2, provided information concerning the non-applicability of the subject bulletin. The response, however, was not signed under oath or affirmation. Consequently, we are forwarding, in accordance with instructions contained in your letter (Reference 1), the response previously filed, with the notarized signature.

Very truly yours,

DAIRYLAND POWER COOPERATIVE

Frank Linder, General Manager

FL: RES: af

cc: U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Division of Reactor Operations Inspection Washington, D. C. 20555

JUN 5 MAN

Corrected T/C

DAIRYLAND
COOPERATIVE • PO BOX 817 • 2615 EAST AV SOUTH • LA CROSSE WISCONSIN 54601
(608) 788-4000

April 18, 1980

In reply, please refer to LAC-6871

DOCKET NO. 50-409

Mr. James G. Keppler
Regional Director
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE

LA CROSSE BOILING WATER REACTOR (LACBWR) PROVISIONAL OPERATING LICENSE NO. DPR-45

IE BULLETIN NO. 80-07 - BWR JET PUMP ASSEMBLY FAILURE

REFERENCE: (1) NRC Letter, Keppler to Linder, dated April 7, 1980.

Dear Mr. Keppler:

Reference (1) forwarded IE Bulletin 80-07, which requires inspection and surveillance of BWR jet pumps. These requirements are not applicable to the La Crosse Boiling Water Reactor due to plant design which does not include jet pumps. No further action will be taken on IE Bulletion 80-07.

If there are any questions regarding this letter, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE

Frank Linder, General Manager

FL:FAD:abs

cc: U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Division of Reactor Operations Inspection Washington, D. C. 20555 Into the strips

Corrected

Mr. James G. Keppler Regional Director LAC-6871 April 18, 1980

STATE OF WISCONSIN )
COUNTY OF LA CROSSE)

Personally came before me this 3rd day of June, 1980, the above named Frank Linder, to me known to be the person who executed the foregoing instrumen: and acknowledged the same.

Oun & Malen
Notary Public, La Crosse County

Wisconsin.

My Commission Expires February 26, 1984.