

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

July 24, 1980

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
Attn: Mr. B. Joe Youngblood, Chief
Licensing Branch No. 1
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Serial No. 653
NO/FHT:ms
Docket No. 50-339
License No. NPF-7

Dear Mr. Denton:

NORTH ANNA POWER STATION UNIT NO. 2
DEGRADED CORE TRAINING STATUS

This letter is to inform you that we have completed the full-power requirements of the North Anna Unit 2 SER Section 10-2 and the TMI Action Plan NUREG 0660 items II.B.4, Degraded Core Training. All Unit 2 licensed operators have received training for degraded core conditions.

Very truly yours,


B. R. Sylvia
Manager - Nuclear
Operations and Maintenance

cc: Mr. James P. O'Reilly

8007250379

V