TERA

1.1.4 of
our submittal
containment
liaries
actuation
tems prior



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

July 2, 1980

Docket No. 50-213

Mr. W. G. Counsil, Vice President Nuclear Engineering & Operations Connecticut Yankee Atomic Power Company P. O. Box 270 Hartford, Connecticut 06101

Dear Mr. Counsil:

We have completed our review of your plans to implement item 2.1.4 of the Category "A" Lessons Learned requirements, as stated in your submittal of May 23, 1980. In that letter you committed to remove the containment isolation valves associated with the reactor coolant pump auxiliaries from the high containment pressure and safety injection system actuation circuits, and to reclassify these auxiliaries as essential systems prior to startup from your current refueling outage. As a result of the changes, these systems would no longer be automatically isolated in the event of a high containment pressure or a safety injection signal. We have determined that these measures constitute an acceptable resolution of the concerns we expressed in our letter of May 7, 1980, regarding Lessons Learned implementation.

Sincerely,

Dennis M. Crutchfield, Chef Operating Reactors Branch #5

Division of Licensing

cc: See next page

cc:
Day, Berry & Howard
Counselors at Law
One Constitution Plaza
Hartford, Connecticut 06103

Superintendent Haddam Neck Plant RFD #1 Post Office Box 127E East Hampton, Connecticut 06424

Mr. James R. Himmelwright Northeast Utilities Service Company P. O. Box 270 Hartford, Connecticut 06101

Russell Library 119 Broad Street Middletown, Connecticut 06457

Board of Selectmen Town Hall Haddam, Connecticut 06103

Connecticut Energy Agency
ATTN: Assistant Director
Research and Policy
Development
Department of Planning and
Energy Policy
20 Grand Street
Hartford, Connecticut 06106

Director, Technical Assessment Division Office of Radiation Programs (AW-459) U. S. Environmental Protection Agency Crystal Mall #2 Arlington, Virginia 20460 U. S. Environmental Protection Agency Region I Office ATTN: EIS COORDINATOR JFK Federal Building Boston, Massachusetts 02203