SALAS OF THE SALAS

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION I 631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

JAN 14 . 30

Docket No. 40-8329

Salem Hospital ATTN: Mr. Anchony Mazzola 81 Highland Avenue Salem, Massachusetts 01970

License No: SUC-1215 Expiration Date: October 31, 1979

Gentlemen:

SUBJECT: NOTICE OF EXPIRED LICENSE

This refers to the telephone discussion between Mr. B. O'Neill of this office and yourself on January 7, 1980. The subject of the discussion was the fact that NRC records show that the Byproduct Materials License identified above has expired and no renewal application has been filed in accordance with Section 30.37 of Title 10, Code of Federal Regulations, Part 30.

From our discussion with your representative we learned that you still possess material which requires a specific NRC license. Your possession of that material without a valid, specific license is a violation of Section 30.3, 10 CFR Part 30. Section 30.3 states:

<u>\$30.3</u> Activities requiring license. Except for persons exempt as provided in this part and Part 150 of this chapter, no person shall manufacture, produce, transfer, receive, acquire, own, possess, use, import or export byproduct material except as authorized in a specific or general license issued pursuant to the regulations in this chapter.

This Notice of Violation is sent to you under the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office a written statement or explanation in reply including: (1) corrective steps which have been taken by you, and (2) corrective steps which will be taken to avoid this happening in the future.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room.

8007280 224

JAN 1 4 1980

Also, you must immediately place the radioactive material on hand in secure storage until such time as you acquire a valid license. No other use of the material on hand or purchase of additional byproduct material is authorized. Include a statement in your reply to this Notice of Violation confirming that you have taken this action and describing the controls that will be exercised over the stored material until such time that you obtain a valid license.

Your reply to this Notice of Violation shall be sent, within twenty (20) days of the receipt of this letter, to Region I, U. S. Nuclear Regulatory Commission, 631 Park Avenue, King of Prussia, Pennsylvania 19406, Attention: Mr. R. O. McClintock, Chief, Materials Radiological Protection Section, Fuel Facilities and Materials Safety Branch. The reply must include a copy of the statement and reports required by the items above.

Since your present license has expired, your application for renewal will be processed as a request for a new license. Accordingly, you must determine if your program is subject to a license fee as required by Section 170.31 of 10 CFR Part 170 and, if one is required, submit the appropriate fee along with the application.

We request that you give prompt attention to these matters. Should you have any questions regarding them, we would be pleased to discuss them with you.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room.

Sincerely,

Robert O. McClintock, Chief Materials Radiological Protection Section

Enclosures: 1. NRC Form 313 2. 10 CFR Part 170