

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	-	0	2	9	3	7	0	7	0	1	8	0	8	0	7	3	1	8	0	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On July 1, 1980 HPCI Turbine Discharge Line Snubber No. S23-3-31 was found severed. On July 16, 1980 an upstream snubber on the same line Snubber #23-3-36 was found severed. On both occasions the HPCI system was declared inoperable and "in kind" replacements installed. Following the July 1, 1980 maintenance the system was satisfactorily tested and returned to service. During the post maintenance testing on July 16, the High Pressure Pump casing gasket was found leaking and had to be replaced. Following its replacement, the system was satisfactorily tested and returned to service.

SYSTEM CODE S F 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE S U P P O R T 14		COMP. SUBCODE D 15		VALVE SUBCODE Z 16	
EVENT YEAR 8 0 21 22		SEQUENTIAL REPORT NO. 0 3 4 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN A 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 40		ATTACHMENT SUBMITTED N 23	
PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER B 2 0 9 26									

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 HPCI System snubbers analysis and modification have been initiated as part of PDCR

1 1 80-47. A transient analysis, utilizing various instrumentation, is planned to

1 2 provide correlation between actual and calculated loads. Temporarily, a 20KIP snubber

1 3 has been added to the system adjacent to the 3 KIP, S23-3-31 snubber. A permanent

1 4 fix is dependent on the results of the transient analysis.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	1 0 0	N.A.		A	Operational Event		
7	8	9	10	11	12	13	14	15	16
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	Z	N.A.		N.A.			
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	Z	N.A.			
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	N.A.				
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	N.A.						
7	8	9	10	11	12	13	14	15	16
PUBLCITY		ISSUED		DESCRIPTION		NRC USE ONLY			
2	0	N	8008040152		N.A.				
7	8	9	10	11	12	13	14	15	16

PHONE

617-746-7900