

July 28, 1980

In reply, please
refer to LAC-7058

DOCKET NO. 50-409

Director of Nuclear Reactor Regulation
ATTN: Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch #5
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBWR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
ADDITIONAL INFORMATION REQUIRED FOR NRC
STAFF GENERIC REPORT ON BOILING WATER REACTORS

- References:
- (1) DPC Letter, Linder to Ziemann, LAC-6486, dated September 7, 1979.
 - (2) NUREG-0578, "TMI-2 Lessons Learned Task Force Status Report and Short-Term Recommendations", forwarded by NRC Letter, dated August 6, 1979.
 - (3) NRC Letter, Ziemann to Linder, dated July 31, 1979.
 - (4) NRC Letter, Ziemann to Linder, dated July 17, 1979.

Gentlemen:

Enclosure 1 of this letter includes revised pages 1, 2, and 6 of Enclosure 1 of Reference 1.

The Safety/Relief Valves section of page 6 has been updated to include direct position indication of the valves in the Control Room. This plant modification was completed in April 1980.

The High Pressure Core Spray section of page 2 has been corrected to include initiation by a 5 PSIG Containment Building pressure signal which serves as the diverse parameter to actuate High Pressure Core Spray.

Pages 1 and 6 have been revised to show that valve position indications in the Control Room for various systems are direct, as described in Section 2.1.3a in Appendix A of Reference 2. Position indication for each of the specified valves is provided by limit switches which give reliable position indication of the valve stem.


Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch #5

LAC-7058
July 28, 1980

If there are any questions regarding this submittal, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE



Frank Linder, General Manager

FL:FD:af

Enclosure

cc: J. Keppler, Reg. Dir., NRC-DRO III