OCT 6 1989

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IL 60690 Docket No. 50-254 Docket No. 50-265

Gentlemen:

This refers to the routine resident inspectors' safety inspection conducted by Messrs. R. L. Higgins, J. M. Shine, D. E. Jones and R. Bocanegra of this office from August 20 through September 23, 1989, of activities at Quad Cities Nuclear Power Station, Units 1 and 2 authorized by NRC Operating Licenses No. DPR-29 and No. DPR-30, and to the discussion of our findings with Mr. R. L. Bax at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as described in the enclosed inspection report. However, because the NRC wants to encourage and support licensee's initiatives for self-identification and correction of problems, the NRC will not generally issue a Notice of Violation for a violation that meets the tests of 10 CFR 2, Appendix C, Section V.G.1. This is the case with the violation discussed in Paragraph 5.b.(1) of the enclosed inspection report. If you do not agree with our statement of your corrective actions, you are requested to inform us, in writing, within 30 days of the date of this letter. Otherwise, no reply to the violation is required and we have no further questions regarding this matter at this time.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room.

8910180277 89100654 BORN ADOCK 85000 DEC ZEO,

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original Signed by J. M. Hinds, Jr."

W. D. Shafer, Chief Reactor Projects Branch 1

Enclosure: Inspection Reports No. 50-254/89020(DRP); No. 50-265/89020(DRP)

cc w/enclosure:
T. Kovach, Nuclear
Licensing Manager
R. L. Bax, Station Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Richard Hubbard
J. W. McCaffrey, Chief, Public
Utilities Division
R. Landsman, TSS

