

DCD/DCB

OCT 23 1989

S. D. Warren Company  
ATTN: Tonia Cianci  
2400 Lakeshore Drive  
Muskegon, MI 49441

License No. 21-09339-01

Dear Ms. Cianci:

This refers to a telephone contact conducted October 5, 1989. The contact was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license.

As a result of this examination of activities, a regulatory concern was noted and is specified below. This may be evaluated at an onsite inspection at your facility in the near future.

- Physical inventories of your cesium-137 and iron-55 sealed sources have not been conducted as required by License Condition No. 15.

You should examine your license and NRC regulations to determine how you can correct the apparent regulatory concern. Please submit to this office within 30 days of this letter, a description of actions taken or those that will be taken to correct the above mentioned regulatory concern.

If you have any questions regarding this contact, you may contact us at (312) 790-5500.

Sincerely,

D. J. Sreniawski, Chief  
Nuclear Materials Safety  
Section 1

cc: DCD/DCB (RIDS)

R111

*WJL for*  
King/jh

R111

*WJL for*  
Sreniawski  
10/10/89

8910310044 891023  
REG3 LIC30  
21-09339-01 PIC

IE07

1/0