## NOTICE OF VIOLATION

Commonwealth Edison Company

Docket Nos. 50-454; 50-455

As a result of the inspection conducted on August 20 through September 30, 1989, and in accordance with the "General Policy and Procedures for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1989), the following violation was identified:

Technical Specification 6.9.1.6 requires that the Annual Radiological Environmental Operating Report include the results of the analyses of all radiological environmental samples taken during the period, at all the locations specified in the tables and figures specified in the Offsite Dose Carculation Manual (ODCM).

Contrary to the above, althoug, the four Annual Radiological Environmental Operating Reports covering the years 1985 to 1988 included summaries, the results of the analyses of the radiological environmental samples taken during the respective periods were not included.

This is a Severity Level IV violation (Supplement VII). (454/89017-02(DRSS); 455/89019-02(DRSS))

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be give to extending your response time for good cause shown.

10-20-89 Dated

Reactor Projects Branch 1