

November 3, 1989

P137

Mr. Wade Green
Institute of Nuclear Power Operations
Suite 1500, 1100 Circle 75 Parkway
Atlanta, Georgia 30339-3064

Dear Mr. Green:

Enclosed for your information is our biweekly listing of generic communications being considered or under development by the NRC staff. These include Bulletins (type coded BL on the list), Information Notices (IN) and Generic Letters (GL). Temporary Instructions, that cover the special NRC inspection effort resulting from certain generic communications, are listed with the type code TI. This listing includes all proposed generic communications that had been reported to us by November 1, 1989.

Sincerely,

Original Signed By
Carl H. Berlinger

Carl H. Berlinger, Chief
Generic Communications Branch
Division of Operational Events Assessment
Office of Nuclear Reactor Regulation

Enclosure:
As stated

DISTRIBUTION w/enclosure:

All NRC Division Directors
All NRC Branch Chiefs
CERossi, NRR
CHBerlinger, NRR
OGCB Members
JThoma, NRR
RFraley, ACRS
JLieberman, OE
PDR
Central Files
DCB
DOEA R/F
OGCB R/F
DKirkpatrick R/F
SRichardson, DOE
RBarber, DOE

OGCB:DOEA:NRR
DCKirkpatrick
11/1/89 *QCK*

CHB
C/OGCB:DOEA:NRR
CHBerlinger
11/1/89

DF03
1/1

RD-25
INPO

PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

TP ORIGIN. OFFICE	SUBJECT	CONTACT	PHONE	ESTIMATED DATE
IN NRR/DRIS RVIB	ENVIRONMENTAL QUALIFICATION OF LIMITORQUE MOV ACTUATOR TERMINAL BLOCKS & MARATHON 1600 TERMINAL BLOCKS	Steve Alexander	(301) 492-0995	12/18/89
GL NRR/DEST EMEB	SUPPLEMENT TO GENERIC LETTER 87-11 DEALING WITH ARBITRARY INTERMEDIATE PIPE RUPTURE REQUIREMENTS	Shou-Nien Hou	(301) 492-0904	04/30/90
GL NRR/DEST ESGB	NRR RECOMMENDATION ON ISI OF MARK I & II STEEL CONTAINMENTS, REFUELING CAVITIES & ASSOC DRAINAGE SYS	Chen P. Tan	(301) 492-0829	12/31/89
GL NRR/DEST SELB	RESOLUTION OF GENERIC ISSUE B-56, DIESEL RELIABILITY	Om P. Chopra	(301) 492-0835	02/28/90
GL NRR/DOEA OTSB	LINE ITEM TECHNICAL SPECIFICATION IMPROVEMENT - REMOVAL OF COMPONENT LISTS	Tom Dunning	(301) 492-1189	01/03/90
GL NRR/DEST ESGB	MINIMUM EDGE DISTANCE FOR INSTALLATION OF ANCHORS IN CONCRETE	John Ma	(301) 492-0827	03/31/90
IN AEOD	THE REPORTING OF SAFETY VALVE AND SAFETY-RELIEF VALVE EVENTS PURSUANT TO 10 CFR 50.73	Mary S. Wegner	(301) 492-7818	11/03/89
GL RES/IEB & RPSIB	RESOLUTION OF: GI/70, PORV AND BLOCK VALVE RELIABILITY, AND GI/94, ADDITIONAL LOW TEMP OVERPRESS PROTECTION FOR LWRS	R Kirkwood E Throm	492-3928 -3911	12/03/89
TI NRR/DEST EMEB	INSPECTION OF IMPLEMENTATION OF GENERIC LETTER 89-10: "SAFETY RELATED MOTOR OPERATED VALVE TESTING AND SURVEILLANCE"	Tom Scarborough	(301) 492-0916	01/31/90
TI NRR/DEST SRXB	INSPECTION OF COMPLIANCE WITH BULLETIN 38-04: "SAFETY-RELATED PUMP LOSS"	Mike McCoy	(301) 492-0880	11/30/89
IN REGION III	FAILURE OF LIMITORQUE VALVE OPERATOR HOUSINGS	John Jacobson	(312) 790-5610	11/03/89

PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

TP ORIGIN, OFFICE	SUBJECT	CONTACT	PHONE	ESTIMATED DATE
IN NRR/DOEA CGCB	OPERATING EXPERIENCE FEEDBACK	Vernon Hodge	(301) 492-1169	11/03/89
GL NRR/DEST SPLB	CONTROL ROOM HABITABILITY SYSTEMS	Charles Nichols	(301) 492-0854	12/31/89
IN NRR/DOEA OGCB	DIESEL GENERATOR FUEL OIL OXIDATION	Vernon Hodge	(301) 492-1169	11/28/89
GL NRR/DOEA OTSB	LINE-ITEM TECH SPEC IMPROVEMENT - ALT REQUIREMENTS FOR FUEL ASSEMBLIES IN DESIGN FEATURE SECTION OF TECH SPECS	Chris Hoxie	(301) 492-3138	11/17/89
GL NRR/DREP PRAB	ACCIDENT MANAGEMENT STRATEGIES FOR CONSIDERATION IN IPE PROCESS - 30 CFR 50.54	R. Palla	(301) 492-1076	01/03/90
BL NRR/DEST ECEB	EVALUATION OF HAZARDS ASSOCIATED WITH HYDROGEN, NITROGEN AND PROPANE USED IN NUCLEAR POWER PLANTS	Frank J. Witt	(301) 492-0823	12/04/89
IN REG V	INGERSOLL-RAND AIR START MOTORS USED ON DIESEL GENERATORS	Don Kirkpatrick	(301) 492-1152	11/03/89
GL NRR/DEST EMTB	GUIDANCE ON TEMPORARY REPAIR OF SERVICE WATER SYSTEM COMPONENTS	Sam Lee	(301) 492-0943	12/31/89
IN NRR/DRIS RSIB	INADEQUATE POST MODIFICATION TESTING	S. V. Athavale	(301) 492-0974	11/24/89
IN NRR/DRIS RSIB	INADEQUATE CONTROL OF TEMPORARY MODIFICATIONS ON SAFETY RELATED SYSTEMS	S. V. Athavale	(301) 492-0974	11/30/89
GL NRR/DEST SELB	GROUNDING IN DIRECT CURRENT DISTRIBUTION SYSTEMS	F. Burrows	(301) 492-0833	12/17/89
IN NRR/DREP PRPB	UNEXPECTED HIGH RADIATION AREAS RESULTING FROM SPENT FUEL POOL ACTIVITIES	John Buchanan	(301) 492-1097	01/31/90
IN NRR/DEST SELB	DEGRADED GRID VOLTAGE	Om P. Chopra	(301) 492-0835	11/10/89
IN NRR/DREP PRPB	RUPTURE OF DECAYED FUEL ASSEMBLY COULD GIVE EXCESSIVE OCCUPATIONAL SKIN EXPOSURES	Charles Hinson	(301) 492-3148	11/20/89

PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

TP ORIGIN. OFFICE	SUBJECT	CONTACT	PHONE	ESTIMATED DATE
TI NRR/DEST EMEB	INSPECTION OF IMPLEMENTATION OF GL 89-04: "GUIDANCE ON DEVELOPING ACCEPTABLE INSERVICE TESTING PROGRAMS"	Ted Sullivan	(301) 492-0901	02/28/90
IN REGION II	UNQUALIFIED OPERATORS PERFORMING LICENSED OPERATOR DUTIES IN THE CONTROL ROOM	Jack Ramsey	(301) 492-1167	11/03/89
IN AEOD/DOA IRB	PROPER AND CONSISTENT REPORTING OF SIGNIFICANT EVENTS TO THE NRC	R. J. Stransky	(301) 492-8578	12/08/89
IN NRR/DOEA OEAB	METHODS FOR EARLY IDENTIFICATION OF A POTENTIAL STEAM GENERATOR TUBE RUPTURE	Bob Benedict	(301) 492-1174	11/17/89
GL RES/DSIR SAIB	SUPPLEMENT TO GL 88-20 INDIVIDUAL PLANT EXAMINATION OF EXTERNAL EVENTS FOR SEVERE ACCIDENT VULNERABILITIES	John T. Chen	(301) 492-3919	02/28/90
TI NRR/DRIS RSIB	ELECTRICAL DISTRIBUTION FUNCTIONAL INSPECTION	S. V. Athavale	(310) 492-0974	01/31/90
IN NRR/DEST SELB	DISABLING OF EMERGENCY DIESEL GENERATORS BY THEIR NUETRAL GROUND-FAULT PROTECTION CIRCUITRY	Fred Burrows	(301) 492-0833	11/17/89
IN NRR/DOEA OGCB	MODEL HK CIRCUIT BREAKERS MISSING ANTI-SHOCK LATCH SPRING	Jack Ramsey	(301) 492-1167	11/15/89
IN NRR/DOEA OGCB	INTERSYSTEM LEAKAGE DUE TO FAULTY CHECK VALVES	Vernon Hodge	(301) 492-1169	11/15/89
IN NRR/DOEA OGCB	BIOFOULING BY ZEBRA CLAMS	Vernon Hodge	(301) 492-1169	11/15/89
IN REGION II	SEIMENS-ITE MOLDED CASE CIRCUIT BREAKER FAILURES	M. Shannon	(919) 362-0601	12/01/89
IN NRR/DOEA OEAB	[NEW] DEBRIS IN CONTAINMENT SUMPS AND INCORRECT SUMP SCREEN CONFIGURATIONS IN OPERATING NUCLEAR PLANTS	Walton Jensen	(301) 492-1190	11/03/89
IN REGION III	[NEW] INADEQUATE SECONDARY CONTAINMENT INTEGRITY SURVEILLANCE TESTING	W. L. Axelson	(312) 790-5574	11/30/89

PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

TP ORIGIN. OFFICE	SUBJECT	CONTACT	PHONE	ESTIMATED DATE
IN NRR/DET EMTB	[NEW] DEGRADED COATINGS AND CORROSION OF STEEL CONTAINMENT VESSELS	Chen P. Tan	(301) 492-0829	11/30/89
GL RES/DSIR EIB	[NEW] POTENTIAL CONCERNS RE PWR REACTOR VESSEL DESIGN ADEQUACY UNDER NATURAL CONVECTION COOLDOWN TRANSIENT CONDITIONS	Joel Page	(301) 492-3941	12/04/89
GL NRR/DST SELB	[NEW] STATION BLACKOUT RESPONSE SUBMITTALS ANALYSES AND RESPONSES	A. Gill	(301) 492-0811	01/03/90
IN NRR/DRIS RSGB	ANALYSING AND CORRECTING SAFEGUARDS PROGRAM FAILURES	Nancy Ervin	(301) 492-0946	12/15/89