

# NRC INSPECTION MANUAL

DRO

Change Notice 19-037

DELETED:		TRANSMITTED:	
<u>Number</u>	<u>Date</u>	<u>Number</u>	<u>Date</u>
1. IMC 0305	06/21/18	IMC 0305	11/25/19
2.			
3.			

TRAINING: No special training is required for any documents issued with this Change Notice.

REMARKS: IMC 0305, "Operating Reactor Assessment Program," has been revised to clarify timing for opening a cross-cutting issue, and to change references to inspecting licensee root cause analyses to inspecting licensee causal analyses for safety-significant findings. Incorporated FBF 0305-2286

## EDITORIAL REVISIONS FROM PREVIOUS CHANGE NOTICES (As Required):

From Change Notice 19-035:

Under the remarks section of Change Notice 19-035, IP 36100.01 is listed at 35100.01, and IP 71153 stated, "...revised to provide oversight guidance associated with licensee adoption of 10 CFR 50.59." This is a typographical error. The correct document is 10 CFR 50.69.

## DISTRIBUTION:

Standard

Official Use Only (OUO)-Security Related Information.

Please contact: \_\_\_\_\_ Phone: \_\_\_\_\_

END