

# NRC INSPECTION MANUAL

DRO

Change Notice 19-037

DELETED:

TRANSMITTED:

Number

Date

Number

Date

- |    |          |          |          |          |
|----|----------|----------|----------|----------|
| 1. | IMC 0305 | 06/21/18 | IMC 0305 | 11/25/19 |
| 2. |          |          |          |          |
| 3. |          |          |          |          |

TRAINING: No special training is required for any documents issued with this Change Notice.

REMARKS: IMC 0305, "Operating Reactor Assessment Program," has been revised to clarify timing for opening a cross-cutting issue, and to change references to inspecting licensee root cause analyses to inspecting licensee causal analyses for safety-significant findings. Incorporated FBF 0305-2286

EDITORIAL REVISIONS FROM PREVIOUS CHANGE NOTICES (As Required):

From Change Notice 19-035:

Under the remarks section of Change Notice 19-035, IP 36100.01 is listed at 35100.01, and IP 71153 stated, "...revised to provide oversight guidance associated with licensee adoption of 10 CFR 50.59." This is a typographical error. The correct document is 10 CFR 50.69.

DISTRIBUTION:

☒ Standard

☐ Official Use Only (OUO)-Security Related Information.

Please contact: \_\_\_\_\_ Phone: \_\_\_\_\_

END