APPENDIX B

NOTICE OF DEVIATION

Duke Power Company

License Nos. DPR-38 DPR-47 DPR-55

Based on the results of the NRC inspection on October 11-19, 1977, it appears that certain of your activities were not conducted in conformance with your commitments to the Commission or generally acceptable practices in the industry as indicated below.

A. Section 12.3.3(c) of the FSAR defines the established outside emergency services and Section 12.3.3(e) commits to annually contacting off site agencies to verify telephone numbers.

Contrary to the above commitment, three offsite agencies - Oconee Memorial Hospital, medical consultants at Memorial Clinic, and the ambulance rescue service - had not been contacted for over two years. This item is a deviation.

B. Section 12.3.3(c) of the FSAR defines the established outside emergency services and Section 12.3.8 commits to simulated drills involving offsite agencies.

Contrary to the above commitment, there has been no participation in any emergency drill by any offsite support agency since June 1975. This item is a deviation.

C. Section IIIA. of the Emergency Procedure states that the auxiliary building first aid room will be equipped with a stretcher, resuscitator, first aid supplies and a monitoring instrument, and that this equipment will be available for handling emergencies. 49CFR Part 173.134 requires the oxygen bottles of the resuscitator kit be hydrostatically tested every five years.

Contrary to the above, the resuscitator kit contained oxygen bottles that had not been hydrostatically tested at the required five-year intervals (bottles stamped 10-66). This item is a deviation.

8001031 050

License Nos: DPR-38 DPR-47 DPR-55

D. Section 12.3.3(c) of the FSAR defines the established outside emergency services and Section 12.3.8 commits to distribution of the Emergency Procedure to all participating outside services.

Contrary to the above commitment, four of the agencies - State Highway Patrol, Oconee County Rural Fire System, Oconee Memorial Hospital and DOE Savannah River, were not on the distribution list for the Emergency Procedure. This item is a deviation.

-2-

E. Section 12.3.3(e) of the FSAR commits to drills to develop and maintain the competence of operating personnel in handling each category of emergency situation.

Contrary to the above, the licensee failed to conduct drills, during the period July 1975 to September 1977, that were structured to develop and maintain the competence of operating personnel in handling each category of emergency situation. This item is a deviation.

...